

✓ STATE Virginia	COUNTY Lancaster	TOWN OR VICINITY Lancaster
INDEX NUMBER 1A, 52-LANC, 1-	MONUMENT Clerk's Office-WINDOW SHUTTER	
REPRESENTED IN NEGATIVE FILE	H.A.B.S. SURVEY NO. VA-360	Owner: The County. Date built:
PUBLISHED PHOTOGRAPHS		18th C. Condition: Fair. Descrip-
PUBLISHED DRAWINGS		tion: Brick, Flemish bond. Notable for
670 6-8369		sheathed and studded shutters: single-leaf, sheathed vertically outside, horizontally within, two thicknesses joined by wrought- iron spikes set in diagonal pattern, clenched on inside--an English practice much followed where strength and economy required, in 17t and 18th C. (see Bettesworth's Builders
10-444		HISTORIC AMERICAN BUILDINGS SURVEY

 1P  
10

HABET

2

✓ 95

Dictionary, London, c. 1732). Shutters locked by iron bar hanging at one joint, crossing diagonally over shutters when closed; bolt passed through hole in end of bar, and window joint fixed with cotter pin on inside.

Prepared by Thomas T. Waterman 1941